

# Safety Data Sheet (SDS)

## Section 1: Chemical Product and Company Identification

**Cat# :** 5701

**Part Name:** Contrex CA

**Supplier:** Decon Laboratories Inc.

460 Glennie Circle King of Prussia, Pa 19406  
SDS Telephone # (610) 755-0800

### Emergency Telephone Numbers

US Chemtrec: (800) 424-9300

Canada: (703) 527-3887

**Identified uses:** Laboratory use

Email Contact: [cveloski@deconlabs.com](mailto:cveloski@deconlabs.com)

## Section 2: Hazards Identification:

### Hazard Overview

**Emergency Overview:** This product can cause strong skin irritation, severe eye and mucous membrane irritant. Immediately flush with water

**Signal Word:** WARNING



### Hazard and Precautionary Statements

H320	Causes eye irritation
H315	Causes skin irritation.
H303	May be harmful if swallowed

### NFPA Rating

Hazard Ratings:

These ratings are Decon Laboratories Inc.'s own assessments of the properties of the material using the ANSI/NFPA 704 Standard. Additional information can be found by consulting in the NFPA published ratings lists (List 325 and list 49).

If no data is listed the information is not available

Health 2      Flammability 0      Reactivity 0

## Section 3: Composition/ Information on ingredients

# Safety Data Sheet (SDS)

Note: Items listed with a CASRN number have no CAS# available

Item#	Name	EINECS	CAS #	% in Product
1	Water Softened		7732-18-5	Major Comp.
2	Citric Acid		77-92-2	Substantial
3	DDBSA		68584-22-5	Substantial
4	Gluconic Acid 50% Liquid		526-95-4	Minor Comp.
5	Surfonic JL-80X		69013-18-5	Minor Comp.

## Section 4: First Aid Measures

### Eye contact

Wash with water for 15 minutes, see a physician if irritation persists

### Skin contact

Wash with water and apply lotion for redness

### Inhalation

Remove to fresh air, give oxygen if needed

### Ingestion

Wash mouth and other contacted part with water

Never give anything by mouth to an unconscious person.

If conscious, give 1-2 glasses of water

Avoid alcohol

Contact a physician or poison control center.

## Section 5: Fire-Fighting Measures

Flash Point, deg. F:	No Flash Point	Method:	Water, foam, ABC Extinguisher
UEL: N/A	LEL: N/A	Autoignition temperature, deg. F:	N/A
Flammability Classification:	N/A	Flame Propagation Rate:	N/A
Hazardous Combustion Products:	CO <sub>2</sub> , H <sub>2</sub> O, Ash		

Special Protective Equipment: Gloves and Safety Glasses

## Section 6: Accidental Release measures

Any information listed below is to be considered in addition to internal guidelines for isolation of spill, containment of spill, removal of ignition sources from immediate area, and collection for disposal of spill by trained, properly protected clean up personnel.

**Personal Protection:** Wear gloves and safety glasses

**Environmental Precautions:** Product is suitable to wash to sanitary sewer

# Safety Data Sheet (SDS)

---

**Cleanup Methods:**

Wash to sanitary sewer, rinse area with water

## Section 7: Handling and Storage

**Handling:** Open container only to use or to remove material for use. Use a clean dry scoop, or pump to remove material. Do not contaminate material with other products.

**Storage:** Store in a clean dry place.

## Section 8: Exposure Controls/ Personal Protection

**Preventative Measures:**

Open container only to use or to remove material for use. Use a clean dry scoop, or pump to remove material. Do not contaminate material with other products.

**Engineering Controls:**

N/A

**Personal Protection:**

The use of eye protection in the form of safety glasses with side shields and the use of skin protection for hands in the form of gloves are considered minimum and non-discretionary in work places and laboratories. Any recommended personal protection equipment or environmental equipment is to be considered as additional to safety glasses and gloves.

**Eyes:** Wear safety glasses at all times when using this product

**Skin:** Wear water proof, rubber gloves when handling this product

**Respiratory:** Normal ventilation is usually sufficient

Chemical-resistant gloves should be worn whenever this material is handled. The glove material has to be impermeable and resistant to the product. Gloves should be removed and replaced immediately if there is any indication of degradation or chemical breakthrough. Rinse and remove gloves immediately after use. Wash hands with soap and water. All glove recommendations presume that the risk of exposure is through splash and not intentional immersion of the hands into the product. Since glove permeation data does not exist for this material, no recommendation for the glove material can be given for the product. Permeation data must be obtained from the glove manufacturer to determine if the glove is suitable for the task.

## Section 9: Physical and Chemical Properties

Formula:	Mixture	Vapor Pressure:	N/A
Formula weight:	N/A	Vapor Density:	N/A
Boiling Point:	Above 200°F	Relative Density:	1.092
Melting Point:	N/A	pH:	1.2



# Safety Data Sheet (SDS)

---

<b>Section 16: Other Information</b>
--------------------------------------

Date of Issue: 12/06/2004

Date of Revision: 05/08/2015

Decon Laboratories, Inc. provides the information contained herein in good faith but makes no representation as to its comprehensiveness or accuracy. Individuals receiving this information must exercise their independent judgment in determining its appropriateness for a particular purpose. Decon Laboratories, Inc. makes no representations or warranties, either expressed or implied of merchantability, fitness for particular purposes with respect to the information set forth herein or to which the information refers. Accordingly, Decon Laboratories, Inc. will not be responsible for damages resulting from the use of or reliance upon this information.

**End of Safety Data Sheet**